



MAINTENANCE MAN DIED DUE TO ELECTROCUTION

Date Of Incident: MARCH 2010

Location : Tamilnadu

Description of the accident:

One of the maintenance technicians in a factory died due to severe electrocution while involved in the maintenance activity.

No. of persons Injured:

One

Potential Root Cause:

Damage electrical cable.

Damage handlamp.

Short-circuit in the electrical items.

Lessons Learnt:

Usage of RCCB in the electrical equipments needs to be implemented to avoid such incidents.

Usage of 24 v hand lamps can avoid such electrical shock.

Over confident of the workman needs to be addressed in our tool box talks.

Photograph:

SEED express its deepest condolence and pray the god to look after the families of the died welder.



Thanks
Dhinakaran for info.

SAFETY AND ENVIRONMENTAL EDUCATION FOR DEVELOPMENT

SEED

For any feedback Mail at: seedforsafety@gmail.com

Accident-015