



SOME ONE IS WAITING FOR YOU BACK AT HOME HOW TO CONTROL FIRE RISK?



FIRE SAFETY

- Do not store flammable substances near source of ignition.
- The storage of equipment should be in designated areas only.
- Do not smoke or open flames in work area.
- Know the location of nearest Fire extinguishers and buckets for handling emergencies.
- Display emergency contact number in storeroom to handle the emergency situation.
- Do not carry hot work like welding inside lift shaft with wooden scaffolds.
- Do not carry hot work like welding near storeroom wherein flammable materials like carton boxes etc. are kept.
- All the welding equipment should be properly turned off after each working shift and at meal works.
- General standards of site housekeeping should be carefully watched by all concerned and accumulations of combustible rubbish are to be minimized and safely disposed of.
- All electrical equipment should be installed and maintained in a safe manner. If there is any doubt about the safety electrical installations, consult an electrician.
- Check all electrical and circuit breakers etc. are of the correct rating and suitable for the purpose. Do not overload the electrical circuit.
- Your cooperation and good common sense will avoid fire risk.

SAFETY FIRST

For any feedback Mail at : seedkallar@gmail.com

www.seedforsafety.in