



WELDER DIED WHILE CLIMBING THE LADDER

Date Of Incident: MARCH 2010

Location : Tamilnadu

Description of the accident:

A welder while climbing through ladder to carry out some welding work in the tank slipped from the top and fell down and died.

No. of persons Injured:

One

Potential Root Cause:

Slip from the ladder.

Lifeline not used while climbing height areas.

Semi skilled workman.

Improper usage of ladder.

Lessons Learnt:

Now a day's most of the technicians are only semi skilled. A proper safety induction with the hazard potential explanation needs to be implemented in all the factories.

Hazard identification of such routine and non routine work needs to be identified in EHS system to reduce such hazards.

Photograph:

SEED express its deepest condolence and pray the god to look after the families of the died welder.



SAFETY AND ENVIRONMENTAL EDUCATION FOR DEVELOPMENT

SEED

For any feedback Mail at: seedforsafety@gmail.com

Accident-014